An aerial photograph showing a large industrial or commercial area that has been completely inundated with floodwater. The water is a dark, murky grey color, covering the ground, parking lots, and surrounding areas. Several large, white, rectangular buildings with flat roofs are visible, some partially submerged. In the foreground, a large, light-colored, corrugated metal roof is prominent. The background shows more industrial buildings and some greenery, all surrounded by water. The sky is clear and blue.


RAPID FLOOD MANAGEMENT ASSESSMENT

**Lesson Learn and Future Direction for Water Policy:
Structure and non-structure flood prevention**

River and Canal Dredging

Non-Effective and Effective Dredging

1) Non-Effective Dredging




Non-Effective and Effective Dredging

2) Effective Dredging: for Short-Term



Non-Effective and Effective Dredging

3) Effective Dredging: for Long-Term







**Excavated soil to the side of
the river bank.**



**Excavated soil to construct
the embankment, but
narrowing the river cross-**



Excavated soil to construct the embankment, but narrowing the river cross-



- 💧 **Original river is wide/shallow**
- 💧 **Dredging does not consider river condition: depth only.**

10/07/2012 18:40



**Excavated soil to construct
the embankment, but very
steep: bank failed
problems**

10/07/2012 17:55



 **Dredging does not consider river condition: sand embankment**



**Sand embankment
erosion**




Embankment

**construction does not
consider water use and
drainage**



**Filling the excavated soil
to the other side of the
river**



Dredging does not consider river condition: foundations of the bridge abutment.




**Backfilling the sides of
the river narrows and the
terrain grew up:
Encroachment**




The natural river: was wide, but building a dyke river narrows.



Recovery river (*Good example*)



Natural river cross-section




Issues to consider

“River and Canal Dredging”

- ❖ **Incorrect dredging is the cause of the budget waste: can not drain water**
- ❖ **What should we do?????**

Monkey Cheeks




เหมือนอ่างรับน้ำฝน
อย่างเดียว ขุดลึกอย่างไร
ก็ไม่มีวันเต็มและไม่ได้
ช่วยรองรับน้ำนอง

**Rainfall
I Pond
Type**



มีทางน้ำเข้าอย่างเดียว
ไม่มีทางระบายน้ำออก จึง
มีโอกาส
น้ำล้นอ่างในที่สุด สร้าง
ความเสียหายให้พื้นที่รอบ

**Inflow
Pond
Type**



แบบที่ถูกต้องคือขุดลึกและให้
มีทางน้ำเข้าและออกเพื่อให้
สามารถรองรับน้ำนอง
และระบายน้ำออกไปใช้
ประโยชน์ได้

**Inflow
and
Outflow
Pond
Type**

**Monkey
y
Cheeks**

ลำน้ำ
River


 **Correct**

ป็นคันทำเป็นแก้ม
ลึงฝิ่งท่อตามคัน
เพื่อให้น้ำเข้า-ออก
โดยการสูบ

**Dyke
with
pumps**

**Floodpl
ain**

**✘
Wron
g**



ได้ความจุเพิ่มขึ้น 65% ของปริมาณดินที่ขุด

ตารางแสดงการสูญเสียความจุเก็บ กักน้ำเนื่องจากการขุด-ถมดินที่ไม่ ถูกต้อง (ไม่ควรทำ)

%ขุดลึกจาก สันดินเดิม สู่ส่วน การขุด	ประสิทธิภาพการกักน้ำ / ปริมาณดินขุด				
	1.00	1.25	1.50	1.75	2.00
50%	0.00	0.20	0.33	0.43	0.50
60%	0.33	0.47	0.56	0.62	0.67
70%	0.57	0.66	0.71	0.76	0.79
80%	0.75	0.80	0.82	0.86	0.88
90%	0.89	0.91	0.93	0.94	0.94

A wide-angle photograph of a large-scale construction or land reclamation site. The foreground is dominated by a dense patch of tall green grass. In the middle ground, a yellow CAT excavator is positioned on a mound of dark, rich soil. To its right, a red tractor is pulling a trailer filled with dark material. Further back, several white trucks are visible, some parked and others in motion. The background shows a flat, cleared area with more machinery and trucks under a heavy, grey, overcast sky. The overall scene depicts a busy industrial or agricultural project.

Monkey cheeks that are not fully effective.

A wide-angle photograph of a large-scale construction or land-clearing site. In the foreground, a yellow CAT excavator is positioned on the left, partially obscured by a pile of dark earth. The ground is a vast, flat expanse of reddish-brown soil, marked with numerous tire tracks. In the middle ground, several white trucks are parked or moving, and a small red tractor is visible. The background shows a line of trees under a heavy, grey, overcast sky. The overall scene depicts a busy industrial or agricultural project.

Monkey cheeks that are not fully effective.

Issues to consider

“Monkey Cheeks”

- 💧 Excavated soil to fill in the area around the pond → inefficient and waste budgets**
- 💧 What should we do?????**

Dyke /
Embankment / Wall



Dyke along the Chao Phraya River



**Temporary dyke
construction**



Original canal



After excavation



**Embankment wall
construction ?????**



Industrial estate dyke



Strong enough???



**คั่นกันดินเดิมมีอยู่แล้ว
ต้องการให้แข็งแรงเต็มที่ โดย
ทำคั่นคอนกรีตตามแนวคั่นดิน**



**Concrete wall :
Engineering????**




























ISSUES TO CONSIDER


“Dyke / Embankment / Wall”

- 🔴 **Dyke construction must not be intruded into the river.**
- 🔴 **With appropriate engineering →
Landscape and**



Regulator / Pump Station


แบบจำลองประตูระบายน้ำบางโฉมศรีก่อนเกิดอุทกภัย



**Bang Chom Sri Regulator:
before flood**

แบบจำลองเมื่อการก่อสร้างแล้วเสร็จ

สะพานรถยนต์ข้ามคลองส่งน้ำชัยนาท-อยุธยา



**Bang Chom Sri Regulator:
after flood**



**Should be
kept as a
memorial
or
demolition?**



ไซฟ่อนเดิมจะรื้อทิ้งทำเป็น
คลองฝาย



New syphon construction




Embankment repairs: But reduced capacity of the canal



**Embankment repairs:
with 5 m high flow
channel at the left bank**



Narrow canal: boat can not pass (3-4 m)



**The original canal is
about 10 meters wide:
boat can not pass**



Regulator repairs: canal is narrower than the original



**Bridge with a wider
channel than the
regulator**



Dyke intrusion canal on both sides.



Dyke intrusion canal on both sides.



Who is wrong???



**Building houses, blocking
off the river.**


Issues to consider

“Regulator / Pump”

- 🔴 **Encroaching river**
- 🔴 **Engineering design**
- 🔴 **What should we do???**



Infrastructure design / Road / Bridge



**Good practice: water can
flow through, and
construced bridges on**



**การใช้หลักการออกแบบทาง
วิศวกรรมที่มุ่งเน้นการอยู่กับ
น้ำแทนการสู้น้ำ**



Expansion of the bridge span.





New piers and old piers



**Save budget, but
narrowing cross-section**



**Cross-section area
reduced**



Troubleshooting???




Appropriate engineering designs???

Issues to Consider

**“Infrastructure design/
Road/ Bridge”**

- 🔴 **Designed to provide a bridge should be at least equal to the width of the river.**
- 🔴 **No design standard???**

The background is a solid blue gradient, transitioning from a lighter blue at the top to a darker blue at the bottom. There are several thin, wavy lines in shades of cyan and light blue that curve across the top of the image, creating a sense of movement and depth.

Road



**Road must not obstruct
the water flow**



**การเน้นการก่อสร้างที่ง่าย
โดยบังคับให้น้ำไหลผ่านไม่ถึง
1 ใน 10 ของทางน้ำเดิม**



ความกว้างของลำน้ำก่อนจะ
มุดลอดถนน



**obstruction natural
drainage**



**Pipes through the streets
was filled**



**ท่อลอดกลม
สำหรับให้น้ำ
ไหลผ่านใต้
ถนน มีดิน
ทรายอุดจน
เกือบตัน**



**Sand filled more than a
half-pipe???**



ลํารางระบายน้ำลงสู่ทะเลที่ถูกร
บกรุก → ยอมทำเป็นรางใหม่
ที่คิดว่าครึ่งหนึ่งของลํารางเดิม



**สภาพลําราง
ถูกใช้เพื่อ
ประโยชน์อื่น**

Issues to Consider "Road"

- 🔥 **No law enforcement to allow construction encroachment river.**
- 🔥 **Engineering design criteria**
- 🔥 **What should we do**



Changing the reclaimed area to the buildings.



**Changing a forest area to
maize fields.**



Destruction of

ปัญหาหลักที่รอ

คำตอบ

- ❶ การบังคับใช้กฎหมายอย่างเคร่งครัดทำไมไม่ได้หรือไม่ได้ตั้งใจทำ ???
- ❷ ไม่มีแผนการใช้ที่ดินที่ชัดเจนสำหรับการอนุรักษ์พื้นที่ต้นน้ำ การใช้พื้นที่เพื่อ

ปัญหาหลักที่รอ

คำตอบ

- 🔴 **หน่วยงานที่รับผิดชอบไม่มี
เครื่องมือและบุคลากรใน
การตรวจสอบก่อนออกใบ
อนุญาตก่อสร้าง**
- 🔴 **มาตรฐานทางวิศวกรรม
???**